

CHICAGO SEA RAY
 31535 N. HIGHWAY 12
 ROUND LAKE , IL 60073
 (815) 385-2720 Fax:(815) 385-7105
 Email:csrservice@chicagosearay.com

577681

RETAIL

31342 NORTH SHORE BANK
 10923 W. MITCHELL ST
 WEST ALLIS, WI 53214

010146
 199MONTEREY
 262
 RGFY0478A999

REQUEST DATE : 04/29/10
 START DATE : 04/29/10
 COMPLETE : 04/30/10
 BOAT ID : 010146
 BOAT NAME :
 LOCATION :
 (H) : (800) 236-1263 (W) : () -

Operation	Type	Status	Date	Part #	Description	Qty	Price	Labor
EM	MECHANICAL INSPECTION-TRADE	R	C					
	CHECK. COMPRESSION OK, ALL		04/30/10		Labor			325.00
	CYLINDERS BETWEEN 155-170 PSI.							
	SEE ATTACHED FOR ISSUES.							
							LABOR :	325.00
							PARTS & LABOR :	0.00 325.00
							OTHER & DISC :	0.00 0.00

COMMENTS: 1999 MONTEREY 262 S/N RGFY0478A999

***SkipperBud's and affiliates are ranked #2 among Industry Magazine's Top 100 Dealers!*

WORK ORDER PRICE SUMMARY

 Total Parts : 0.00
 Total Labor : 325.00
 Total Other Chgs. : 0.00
 Misc. Supplies : 0.00
 Equipment Charges : 0.00
 Freight Charges : 0.00
 Mileage Charges : 0.00
 Sublet Charges : 0.00
 Environ. Charges : 0.00
 Shop Supplies : 0.00
 Total Labor Disc : 0.00
 Total Parts Disc : 0.00
 Sales Tax : 0.00
 =====
 325.00


Your outstanding balance as
 of 04/30/10 is : 871.40

PRE-OWNED VESSEL APPRAISAL FORM:

Stock # _____

Vessel Year: 99	Make: MONTEREY	Model: 202 Cruiser	Length:	Beam:	Drift:	Use: (Circle One) Salt Fresh
Location of Vessel: Merve 5.7	Hull Configuration: Thunderbird	Transom Name:	Estimated Hours:	Weight:		
Engine Year:	Make & Model: Single <input checked="" type="checkbox"/> Twin <input type="checkbox"/>	HP:	Approximate MPH:	Top End / Cruise		
Fuel Type (Circle One) Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/>	Engine Type (Circle One) OB <input type="checkbox"/> IN <input type="checkbox"/> IO <input type="checkbox"/> Jet <input type="checkbox"/>	Documentation/Registration #:	Color:			
Trailer Year:	Make & Model:	Fuel Tank/Gallons:	Water Tank/Gallons:			
Lienholder	Amount:	Service Contract	NO <input checked="" type="checkbox"/> YES <input type="checkbox"/>	Exp. _____		

Interior Layout
 Exterior Layout



GALLEY & LAUNDRY:

- Dishwasher
- Laundry: Washer Dryer Combo
- Galley Up Down
- Garbage Disposal
- Icemaker: Cockpit Galley
- Refrigerator: Cockpit Galley
- Freezer
- Water Heater
- Water System: Pressure Manual Dockside
- Trash Compactor
- Coffee Maker
- Stove: Electric Alcohol Portable
- Head: Electric VacuFlush Manual Porta
- Oven: Oven Convection Microwave
- Dinette
- Interior Wood: Cherry Maple Other:

ELECTRONICS & NAVIGATION EQUIPMENT

- Autopilot
- Compass
- Depth Scander: **Depth finder**
- Loran/GPS
- Radar
- Chart plotter
- VHF Radio
- Engine Synchronizer
- Stereo: AM/FM Cassette Player Changer
- TV: 1 2 3
- VCR: 1 2 3
- DVD: 1 2 3
- Sun log
- Depth Finder
- Fish Finder
- Satellite TV System
- Lower Station
- EPIRB

Check off those items which appear on the vessel. Note in the lines given any options that are not in good working condition. Add any additional items which are not listed or make note of any necessary information such as description of extreme conditions, repairs needed, etc.

ACCOMODATIONS-FURNISHINGS- LAYOUT:

Seating Style: _____

Model Type Code/Description: _____

Total Heads: _____

Total Staterooms: _____

Total # Sleeps: _____

ELECTRICAL SYSTEMS:

- Battery: 1 2 3
- Battery Switch
- Battery Charger
- Dockside Power: 30 50
- Dockside Cord
- Generator: _____ kw
- Sound Box
- Electrical Systems: 12 Volt 24 Volt Other
- Central Vac
- Converter
- Macerator
- Desalinator

No batteries in boat

MECHANICAL EQPT & ENGINE DETAILS:

- Air Conditioner: ___ Cabin: 1 2 3 ___ Cockpit
- Bilge Blower
- Bilge Pump
- Bow Thruster
- Controls: ___ Cabin ___ Bridge ___ Side ___ Center Cockpit
- Engine Alarm
- Fire Extinguishing Syst: ___ CO² ___ Halon ___ Auto ___ Man
- Fresh Water Cooling System
- Fuel Shut Off Valve
- Fume Detector: ___ Engine ___ CO² Monitor
- Extra Props: ___ SS' ___ Aluminum ___ Brass
- Steering: ___ Manual Hydraulic
- Engine Synchronizers
- Trim Tabs
- Hydraulic Swim Platform
- Cable Master
- Power Trim
- Hour Meter: 351 Hours
- Transom Trailer Switch
- Closed Cooling
- Thru-Hull Exhaust: ___ Mufflers ___ Captains Call
- Underwater Exhaust

DECK EQUIPMENT:

- Anchor w/ Lines
- Anchor Davit
- Bow Pulpit w/ Rail
- Deck Wash Down System
- Dinghy: _____ Make _____ Motor
- Dinghy Davit System
- Fenders & Lines
- Windlass: Electric Manual
- Windshield Wipers
- Deck Sun Pad
- Filler Cushions
- Spotlight
- Transom Shower
- Radar Arch: ___ Forward ___ Back
- Walk-through windshield
- Ski Tow

Missing fire extinguishers

CANVAS & HARDTOP: Color:

- Bow Cover
- Cockpit Cover
- Mooring Cover
- Bimini Top
- Convertible Top
- Side/Aft Curtains
- Camper Canvas
- Aft Deck: ___ Hardtop ___ Enclosure
- Bridge: ___ Hardtop ___ Enclosure

FISHING EQUIPMENT & SAILS/RIGGING:

- Downriggers
- Live well
- Outriggers
- Electric Trolling Motor
- Aux. Motor: ___ Gas ___ Diesel
- Shaft/Rudders

TRAILER: # Axles 2

- Galvanized
- Roller
- Bunk
- Brakes: 1 2 3
- Swing Tongue
- Winch
- Spare

*BRAKE MASTER CYLINDER
EMPTY WILL NEED MAJOR BRAKE
WORK*

MAINTENANCE HISTORY:

Did a dealer service the vessel? Yes No Dealer Name:

EXCLUSIONS: (OTHER THAN PERSONAL ITEMS)

Rate the following based on a scale of 1 to 5.

1= Poor or in need of repairs 3=Average or in working condition 5=Superior: Recently installed and/or replaced

Vessel:

- 2 Deck
- 2 Gunnel Molding
- 2 Hull
- 2 Floor/Carpeting
- 2 Exterior Vinyl
- 2 Interior Upholstery
- 3 Mechanical Rating
- 1 Outdrive Rating
- 3 Performance
- 3 Overall Rating

Trailer:

- 1 Suspension
- Paint
- 1 Brakes

Canvas:

- 2 Color
- 2 Cosmetic Condition
- 2 Zippers/Snaps/Seals
- 2 Fit & Coverage

Customer's Estimated Value: \$ _____

ADDITIONAL COMMENTS MAINTENANCE OR REPAIRS NEEDED:

I certify my trade must be in good working condition (unless otherwise stated) and that I am responsible to provide all equipment checked. If equipment promised is not provided or working, or if engine repairs are necessary, I will be charged and agree to pay for necessary repairs or reappraisal of my trade-in vessel. All holes left from the removal of equipment not included on vessel must be repaired or covered up in a professional manner prior to vessel being dropped off at the dealership. I understand that my trade-in vessel must be available for an out of the water inspection 72 hours prior to closing and/or possession of my new boat.

Owner's Name AND Co-Owner's Name must be identical to the title work.

Owner's Name:	Co-Owner's Name:	Email:
Address:		City, State & Zip:
Home #:	Work #:	Cell #:
		Fax #:

Owner's Signature

Co-Owner's Signature

Dated: _____

MECHANICAL INSPECTION:

Date 9/30/10 Tech Jeh K

Compression: (P) 170 170 170 160
155 160 165 170

(S) 1 2 3 4
5 6 7 8

Generator: 1 2 3 4

Check Operation:

Good	Poor		Good	Poor	
<input checked="" type="checkbox"/>	<input type="checkbox"/>	Water	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Oil Pressure
<input checked="" type="checkbox"/>	<input type="checkbox"/>	Starter	<input type="checkbox"/>	<input type="checkbox"/>	Volts <u>Gauge fell 0</u>
<input checked="" type="checkbox"/>	<input type="checkbox"/>	Temperature	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Bellows/Hoses
<input type="checkbox"/>	<input checked="" type="checkbox"/>	Fluid Level(s)	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Trim/Tilt
<input type="checkbox"/>	<input checked="" type="checkbox"/>	Gear Lube	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Tachometer
<input checked="" type="checkbox"/>	<input type="checkbox"/>	Shift Adjust	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Pull drive
<input type="checkbox"/>	<input checked="" type="checkbox"/>	Distributor	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Gauges
<input type="checkbox"/>	<input checked="" type="checkbox"/>	Load test Batteries	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Horn
<input type="checkbox"/>	<input checked="" type="checkbox"/>	Check alignment	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Bilge Pump
<input type="checkbox"/>	<input checked="" type="checkbox"/>	Navigation lights	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Bilge Blower
<input type="checkbox"/>	<input type="checkbox"/>	Moisture check hull, transom, stringers, and deck			

Additional Comments - Maintenance/Repairs Needed:

See Attached

Service Manager: _____

Estimate attached: Yes No

INTERNAL LISTING INFORMATION:

Price: \$ _____ ACV: _____

Note anything on the previous pages that should be amended:

Rate the following based on a scale of 1 to 5.

- 1= Poor or in need of repairs
- 3=Average or in working condition
- 5=Superior. Recently installed and/or replaced

Vessel:	Trailer:
<u>2</u> Deck	<u>1</u> Suspension
<u>2</u> Gunnel Molding	<u>1</u> Paint
<u>2</u> Hull	<u>1</u> Brakes
<u>2</u> Floor/Carpeting	
<u>2</u> Exterior Vinyl	Canvases:
<u>2</u> Interior Upholstery	<u>2</u> Color
<u>3</u> Mechanical Rating	<u>2</u> Cosmetic
<u>1</u> Outdrive Rating	<u>2</u> Fit & Coverage
<u>2</u> Performance	<u>2</u> Zippers/Snaps

Vessel Serial #: RGFY0478A999

Engine Serial #: (P) OL337991

(S) _____

Trailer Serial #: N/A

Picture taken

Marketing Statement:

- Dash panel has cracks
- Drive needs to be sanded and painted
- Needs Prop repair
- Cracks in cockpit by sink in fiberglass
- Blower is really noisy
- Back Anchor light inop
- TRIM IS INOP DRIVE DOESNT TRIM UP OR DOWN OR TRAILER
- Gear lube reservoir is empty gearlube in drive looks milky
- No batteries
- Stereo works but some buttons down
- Shower pump constantly on
- One of the gauges fell down behind dash
- Cabin moldy had a foot of water in it
- No keys
- Cabin up holstery and ceiling moldy look waterlocked
- Countertop in cabin has big cracks
- fridge in cockpit inop
- Needs a gimbal ring and upper shaft really loose
- Needs tune up Sparkplugs fould out
- Needs Engine Alignment
- Needs Bell housing is broke on bottom
- Needs Major brake job master cylinder empty
- Port side scratch in gel
- Needs full detail very dirty